

Schnittgeschwindigkeit	P1	P2	P3	M1	M2	K1
Vc m/min	10-13	8-11	8-11	6-8	5-7	5-8